

Date: Wednesday, 7/11/2007 2:47:40 PM
 User: Kim Johnston

Process Sheet

SPIT 32

Customer : CU-DAR001 Dart Helicopters Services Drawing Name : LONG STEP ASSEMBLY HIGH SKID LH
 Job Number : 33482
 Estimate Number : 10270
 P.O. Number : *NIA* Part Number : D350591311
 This Issue : 7/11/2007 S.O. No. : *NIA* Drawing Number : D3272 REV B
 Prsht Rev. : NC Project Number : N/A
 First Issue : *NIA* Type : LARGE FAB ASSY Drawing Revision : B
 Previous Run : 33377 Material : *NIA*
 Due Date : 8/10/2007 Qty: 10 Um: Each
 Written By : *[Signature]*
 Checked & Approved By : *[Signature]*
 Comment : Est Rev:A 04.03.22 New issue KJ/RF
 Est Rev:B 07-06-09 Added D3272-1 JLM

Additional Product

Job Number:



Seq. #: Machine Or Operation: Description :

1.0 DC DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Photocopy bluefile and type labels as per PPP D350-591-311 CHG001

10

2.0 D32721 STEP



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

STEP

BATCH: *33372*

[Signature]

KE.07.07.30

3.0 D30671 End Plate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D3067-1 End Plate *3.32836*

KE.07.07.26

4.0 D32191 Support



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 D3219-1 Support *3.33428*

KE.07.07.26

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 7/11/2007 2:47:40 PM

User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID LH

Job Number: 33482

Part Number: D350591311

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel end for welding FWD ONLY

2-Weld Support using Jig DT8719, weld Fwd End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod

M103294
M104721

3-Grind End Plate flush

a.m.

07.07.20

10

H. 07.07.26 10
H. 07.07.26 10

6.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

7.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

En 07/07/30 (10)

8.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

a.m. 07.07.30

10

9.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

En 07/08/02 (10)

10.0

D3065041

Step Leg Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

1 D3065-041

Step Leg Assy

B32032

a.m. 07.08.09

(10)

11.0

D30661

Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total: 20.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

2 D3066-1

Spacer

B338570
B33100148

a.m. 07.08.14

10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 7/11/2007 2:47:40 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID LH

Job Number: 33482

Part Number: D350591311

Job Number:



Seq. #:

Machine Or Operation:

Description :

12.0

MS20600AD4W4

Rivets



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick:

Qty Part Number Description Batch

16 MS20600AD4W4 Rivet 36xM104715 M10394715 a.m 07.08.09 10

13.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

Assemble Leg Assembly as per Dwg D3272.

Leave one rivet out until welding is complete.

a.m 07.08.09 10

14.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

07.08.14 10

15.0

D30671

End Plate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D3067-1 End Plate 330225
332836

07.08.14 10

16.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel Aft end for welding

2-Inspect for foreign object as per QSI 024

3-Weld Aft End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod M103794

4-Grind End Plate flush

a.m 07.08.20

5-Install last rivet as per Dwg.

a.m 07.08.20

10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 7/11/2007 2:47:40 PM

User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID LH

Job Number: 33482

Part Number: D350591311

Job Number:



Seq. #:

Machine Or Operation:

Description :

17.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

07/08/20

18.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

So 07/08/20 (X 10L)

19.0

HAND FINISHING1

HAND FINISHING RESOURCE #1

Comment: HAND FINISHING RESOURCE #1
touch up alodine

BR / FEL 07-08-22 (10)

20.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

M 105068

FEL/BR 07-08-22 (10)

21.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Wing Walk as per Dwg D3272 and QSI 005 4.4

M 104942

M-F 07/08/23 (10X)

22.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: Inspect Powder Coat and Wing Walk

Jx10 7/8/22 SP (10X)

23.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

24.0

D22303

Mounting Lug



Comment: Qty.: 4.0000 Each(s)/Unit Total: 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 D2230-3 Mounting Lug

B30993

SP 7/8/10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID LH

Job Number: 33482

Part Number: D350591311

Job Number:



Seq. #:

Machine Or Operation:

Description :

25.0

D2618

Bushing



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2618

Bushing

1331831

SC

26.0

D2856400

Abrasion Strip



Comment: Qty.: 0.6000 f(s)/Unit Total : 6.0000 f(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2856-400-720 Abrasion Strip

1330992

SC

27.0

D32351

Mounting Lug



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D3235-1

Mounting Lug

1330996

SC

28.0

D3278041

Support Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

1 D3278-041

Support Assembly

1331838

SC

29.0

AN335A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN3-35A

Bolt

1104021

SC

30.0

AN413A

Bolt



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 AN4-13A

Bolt

1104746

7/8/13 SC

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 7/11/2007 2:47:40 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID LH

Job Number: 33482

Part Number: D350591311

Job Number:



Seq. #:

Machine Or Operation:

Description :

31.0

AN536A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN5-36A

Bolt

M104625

SP

32.0

AN960JD10

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD10

Washer

M104885

SP

33.0

AN960JD416

Washer



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

16 AN960JD416

Washer

M104215

SP

34.0

AN960JD516

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD516

Washer

M104154

SP

35.0

MS21042L3

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L3

Nut (or-3)

M104936

7/8/13 SP

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: 1 Date: 07/01/02
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 7/11/2007 2:47:40 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID LH

Job Number: 33482

Part Number: D350591311

Job Number:



Seq. #:

Machine Or Operation:

Description :

36.0

MS21042L4

Nut



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 MS21042L4

Nut (or -4)

M102552

SP

37.0

MS21042L5

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L5

Nut (or -5)

M104018

3/8/13

SP

38.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



2070823

** Placed kit*

in individual



Comment: INSPECT 100% KITS FOR COMPLETENESS

bags.

39.0

PACKAGING 1

PACKAGING RESOURCE #1



B W 07-08-25



(9)

Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D350-591-311

Location:

13 3/8/24

SP

(1)

40.0

QC21

FINAL INSPECTION/W/O RELEASE



(10)

Comment: FINAL INSPECTION/W/O RELEASE

07/14/27

Job Completion



W 07-08-27

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>CP</i>	DRAWN BY <i>B</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>CE</i>	APPROVED <i>H</i>	DRAWING NO. D3272	REV. B SHEET 1 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE NTS
A	04.03.01	NEW ISSUE	
B	07.05.18	D3272-1 WAS D2622-120	

RELEASED

07 06 04 *H*



QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	X	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP.
16	16	MS20600AD4W4	RIVET

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.


SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. *33482*

Copyright © 2004 by DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART

DESIGN	APPROVED	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED	CE	APPROVED	REV. B
DATE	07.05.18	DRAWING NO.	D3272
		TITLE	STEP ASSEMBLY, HI LONG
		SHEET 2 OF 3	SCALE 1:20



D3272-041 STEP ASSEMBLY (LH. SHOWN)
D3272-042 STEP ASSEMBLY (RH, OPPOSITE)






DESIGN <i>GP</i>	DRAWN BY <i>JB</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE 1:20

RELEASED


07.06.04 *[Signature]*



DETAIL C

B D3272-1 STEP

(MAKE FROM D2622-120 STEP EXTRUSION)



DETAIL C
(SCALE 1:5)

DRILL $\phi 0.128$ (#30) FROM JIG ON
BOTH SIDES OF D3272-1 EXTRUSION
TO MATCH D3065-041 HOLE PATTERN

SHOP COPY
RETURN TO
ENGINEERING
CONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 33482

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.